



Norman H. Bangerter  
Governor  
Suzanne Dandoy, M.D., M.P.H.  
Executive Director  
Kenneth L. Alkema  
Director

State of Utah  
DEPARTMENT OF HEALTH  
DIVISION OF ENVIRONMENTAL HEALTH

Bureau of Water Pollution Control  
288 North 1460 West, P.O. Box 16690  
Salt Lake City, Utah 84116-0690  
(801) 538-6146

Mine Feb  
m/035/009

RECEIVED  
SEP 8 1988

DIVISION OF  
OIL, GAS & MINING

August 31, 1988

Mr. Randy Drummond, P.E.  
Kearns Improvement District  
5350 West 5400 South  
P.O. Box 18608  
Kearns, Utah 84118

Re: B.P. Minerals  
Barney's Canyon Project

Dear Mr. Drummond:

We appreciate your comments expressed in your 22 July 1988 letter concerning the B.P. Minerals Barney's Canyon project.

We note that information was transmitted to your office by B.P. Minerals America in their letter of 3 August 1988 concerning the Heap leach pad foundation, liner and leak detection system.

In a phone conversation with you on 30 August 1988 Mr. Charlie Dietz of my staff concluded that your concerns have been adequately addressed.

Please call Mr. Charlie Dietz if you have any additional concerns about this project.

Sincerely,

Utah Water Pollution Control Committee

Don A. Ostler, P.E.  
Executive Secretary

cc: Mr. Gerald Schurtz, B.P. Minerals America  
Mr. Gregory Boyce, General Manager, Barney's Canyon Mine  
Mr. Kent Miner, Salt Lake City/County Health Department  
Mr. Brian Buck, JBR Consultants  
Mr. Lowell Braxton, Division of Oil, Gas & Mining

CGD/ag

4020y-54